

Service Letter: 457

Date: February 10, 2022

Title: Lycoming Electronic Ignition System Placard


Models: 8GCBC (S/N's 611-2021, 614-2021, 615-2021, 616-2021, 617-2021, 618-2021)

Description: There was an error made in production where the required placard for the Lycoming EIS system may not have been installed on the instrument panel in a few select aircraft. This service letter outlines the procedures necessary to apply the required placard to the instrument panel on those aircraft equipped with the Lycoming EIS system.

Required Parts  
11-1264 Placard


Procedure

1. Determine if placard 11-1264 is missing. 11-1264 placard is shown below in Figure 1.



**Figure 1: 11-1264 Placard**

2. If the placard is missing, apply placard to instrument panel. Clean instrument panel prior to application. Placard is to be centered below the radio stack. Placement can be seen in Figure 2.



**Figure 2: 11-1264 Placard Placement**